PLACE Analysis Key Messages / September 2021

East Broyle



Crossing roads within the estate is safe and easy but St Pauls Rd not so much.



The open plan design is being spoilt by hedging to enclose gardens.



Redesign the junction at the entrance to Norwich Road. It can be difficult to get out of the estate. Add a pedestrian and cycle crossing.

The Pallants



Restrictions for commercial vehicles would be helpful.



At times there has in the past been considerable noise from the pubs in South Street.



Apart from the walls walk all remaining areas of open space are all surfaced with tarmac which give little pleasure to the senses.

West Walls



Brewery Field needs to be more accessible and integrated into the street scene. It is currently badly underused.



Make the new roundabout "extra special" as a contemporary portal to the Cathedral and a statement of quality re the city.



Orchard Street is not suited to its traffic levels. Reduce traffic with a city bypass which works.

Westgate



The Old Tannery Site area is unused and unsightly. An appropriate redevelopment of this site would be a significant improvement.



The paving needs to be restored in keeping with character of the Conservation Area.



The volume and speed of traffic along Westgate has been an ongoing concern for residents in the area.

Summersdale



Cycle and walk ways could be signposted better.



The area has habitat for wildlife, but these areas need maintenance to encourage wildlife.



Roads and footpaths could be better maintained.



New Park Road Area



At night time drunken revellers from the pubs makes the area along East St and New Park Road car park feel unsafe.



Pedestrian and cycling routes and safety need improvement.



Lighting needs some thought. The very bright lights in New Park car park is very disturbing to local residents. However, the path along the East Wall is very dark at night and would benefit from being brighter.

Arun Park Estate



Arun Park Estate has no community building.



There is need for a pedestrian crossing from Royal Close (elderly/sheltered housing) to the Co-Op on Bognor Road.



Over time some of the play areas have become less well used and some areas have a slightly neglected feel to them.

Newtown



There have been problems with strong smells and waste collection from restaurants and there are many unsightly air conditioning heat exchangers on commercial properties.



Visitors have trouble finding landmarks and buildings they want to visit.



Pavements and road surfaces are poorly maintained.

Southern Gateway

Many of the cycle routes are extremely dangerous.

otherwise much of the tree cover will be lost.

The majority of trees within the city centre are under threat

safety. A long term planting stratgey needs to be agreed,

Access from the railway station to the city is poor, it is not an

through age, health and pressures of development and public

City Centre

attractive walk.



It is perceived as the scruffy end of the city but that is because people do not know the cul-de-sac street patterns.



Stockbridge Road and Kingsham Road are busy "rat run" roads. By becoming a low traffic neighbourhood (LTN) the area would not be influenced so heavily by traffic movements.



There is not enough space at the Canal Basin to cope with the increased use.

Whyke

The A27 causes noise and pollution issues.



The candle factory causes a nuisance because of unpleasant smells.



Parking restrictions lead to increased traffic speeds as there are no parked cars to slow the traffic. But street parking causes bad visibility. This makes crossing dangerous.





